



POST OFFICE ENGINEERING DEPT S BRANCH	
DISTRIBUTION RESTRICTED	
REFERENCES	
SEE SCHED DBR/329	SPEC. D1000
DSP/1461	SPEC. 5614
ASSEMBLY ORG.	WIRING DGM.
FILE 2388	SPEC. 5614
SCALE: 1 AND AS INDICATED	THIRD ANGLE PROJECTION
DECIMAL DIMENSIONS NOT TOLERANCED SUBJECT TO	
APP'D IN S1 SECTION	DRN. CONT'S/A TCD. B. J. H. CKD. <i>[Signature]</i> DATE 8-9-61
AMENDMENT SUFFIX	
ITEM 2 PICTORIALY AMENDED IN ACCORDANCE WITH MODIFIED LABEL 27-2-63	A
ITEM 1 DELETED ITEM 3 WAS MECH. No. 20 (MK. 1) EXT. 8-8-61	B
ITEM 3 WAS MECH. No. 20A PICTORIALY AMENDED 1-11-67	C



TYPICAL MARKING
G.P.O. 700 FHB/1
(SEE SPEC. D1000)




Dial first - pay on answer
 Dialling codes and charges are shown in the booklet

HAVE MONEY READY, but do not insert yet
LIFT RECEIVER, listen for dialling tone, and
DIAL carefully - then wait for a tone
 Ringing tone changes, when number answers, to
Pay tone (rapid pips) - Now PRESS in a coin
 (Coin slots are shut until first pay tone)

INSERT MORE MONEY on dialled calls
 at any time during conversation, or
 at once if pay tone returns

For the Operator dial 100
For Emergency Calls dial 999



ADJUST GRUB SCREW TO BEAR AGAINST PART 1/DBR/329 (DRG. DBR/329) SO THAT THERE IS NO MOVEMENT OF MECHANISM ON INSERTION OF COINS

PART 1/DSP/1461 (DRG. DSP/1461) TO BE ADJUSTED TO LOCK BOTTOM OF MECHANISM

SCHEDULE			
ITEM	DESCRIPTION	DRG.	No. OFF
* 1	BOX No. 4 (MK. 1)	91015	1
2	CONTAINER No. 6	91341	1
3	MECHANISM No. 21	92159	1

* ITEM TO BE REQUISITIONED SEPARATELY & FITTED LOCALLY

FOR SUPERSED

BOX, COIN-
COLLECTING No. 700
(MARK 1)