

CIRCULATION
GENERAL

TELEPHONE No. 232. C.B.

ANTI-SIDE-TONE INDUCTION COIL TELEPHONE— AUTOMATIC AREAS.


N. 332. 9-4-35
5 PANELS-1

SUPERSEDED BY N 332 (PANELS 4 & 5)
FOR NEW WORK

19/1	28	F
13-17	D	
7-17	C	
16-2-35	B	
6-235	A	

TELE. No. 1/232... (Wk. 2) AND
PANELS 4 & 5 ADDED.
Sheet 2 rechecked.
Sheet 2 rechecked.
Suppression Note Added & Dial No. 411-688 Directed
(Sul) Set. No. 26. Redrawn

AMENDMENT



- NOTES -
1. REMOVE STRAP BETWEEN 7 & 8 ON "BELL SET No. 26" & FIT EXTENSION BELL IF REQUIRED.
 2. THE APPROPRIATE "DIAL, AUTO." TO BE REQUISITIONED SEPARATELY & CONNECTED AS SHOWN.

Y

TELEPHONE No. 232... & 1/232...


FOR USE WITH BELL SET No. 26 ON C.B. & AUTO SYSTEMS ON DIRECT EXCH. LINES ETC. (SEE N 4300 FOR CONNEXIONS)

N 332
2 PANELS-1
16-12-36

GENERAL

24-11-54 F
19-7-50 E
15-4-51 AC

PANELS 1, 2 & 3 CANCELLED, PANELS 4 & 5 MADE
1 & 2. NOTES 3 & 4 ADDED.
TELE. No. 1/232... (Wk. 2) & PANELS 4 & 5 ADDED.
15-4-51 AC & 15-4-51 AC AMENDED
SEE SUPERSEDED TRACING.



- NOTES:-
1. ON TELES. No. 1/232... TO EARLIER PATTERN THE CONNEXIONS TO TERMINALS 6 & 8 ARE REVERSED.
 2. THE LABEL DGM. FOR TELE. No. 1/232... TO BE TO DIMENSIONS GIVEN.
 3. IN EARLIER ISSUES THE CONNEXIONS TO DIAL TERMINALS 1 & 2 WERE REVERSED.
 4. EARLIER ISSUES WERE FITTED WITH COIL INDUCTION No. 20 OR 24.

*: TERMINALS 3 & 4 ARE STRAPPED BY "LINK, BRASS No. 6" ON "TELEPHONE No. 1/232 C.B." AND THE DIAL OMITTED.

W

